

Dispersion:-

To monitor dispersion parameter or process variability different control charts are used. R-chart & S-chart

R-chart:-

To monitor dispersion parameter σ R-chart is a very simple chart used for this purpose. R-chart is based on sample range.

Consider X_1, X_2, \dots, X_n be a random sample from distⁿ with mean μ & variance σ^2 . Let $X_{(1)}$ is the smallest observation & $X_{(n)}$ is the largest observation in the sample. Then range can be defined as:

$$R = X_{(n)} - X_{(1)}$$

$$\text{Range} = \text{Max value} - \text{Min value}$$

This R will be used as plotting statistic.

Now consider

$$w = \frac{R}{\sigma}$$

be a relative range

$$E(\bar{w}) = E\left(\frac{R}{\bar{\sigma}}\right) = d_2$$

$$E\left(\frac{R}{\bar{\sigma}}\right) = d_2$$

$$\frac{E(R)}{\bar{\sigma}} = d_2$$

$$E(R) = d_2 \bar{\sigma}$$

$$\mu_R = d_2 \bar{\sigma}$$

where d_2 is a function of sample size n
i.e. $d_2 = f(n)$ & this value can be found
from the table from the appendix of the
book.

$$SD(\bar{w}) = SD\left(\frac{R}{\bar{\sigma}}\right) = d_3$$

$$S.D\left(\frac{R}{\bar{\sigma}}\right) = d_3$$

$$\frac{S.D(R)}{\bar{\sigma}} = d_3$$

$$S.D(R) = d_3 \bar{\sigma}$$

$$\sigma_R = d_3 \bar{\sigma}$$

where d_3 is a function of "n".
Now the control limits for \bar{R} -chart are as

$$UCL = E(R) + 3SD(R) = d_2 \bar{\sigma} + 3d_3 \bar{\sigma}$$

$$CL = E(R) = d_2 \bar{\sigma}$$

$$LCL = E(R) - 3SD(R) = d_2 \bar{\sigma} - 3d_3 \bar{\sigma}$$

$$UCL = \overbrace{(d_2 + 3d_3)}^{D_2} \bar{\sigma} = D_2 \bar{\sigma}$$

$$CL = d_2 \bar{\sigma} = D_1 \bar{\sigma}$$

$$LCL = \overbrace{(d_2 - 3d_3)}^{D_1} \bar{\sigma} = D_1 \bar{\sigma}$$

where D_1 & D_2 are function of sample size n
 & can be found from table.

Now if any sample range falls out of these limits process is considered to be out of control
 otherwise process is in-control